

Karuah Hard Rock Quarry

Summary of Environmental Monitoring Data



For the Period: December 2017

1. Introduction

This report has been completed to meet the requirements of Section 66(6) of the *Protection of the Environment Operations Act 1997* and the NSW Environmental Protection Authority's (EPA) *Requirements for Publishing Pollution Monitoring Data* (October 2013). This report summarises the required monitoring data under Environmental Protection Licence (EPL) 11569 for the Karuah Hard Rock Quarry (Karuah Quarry). This report also includes some monitoring requirements under Development Consent (DA 265-10-2004).

A summary of the environmental monitoring data for <u>December 2017</u> is covered in this report.

A summary of the licence information is provided in the tables in the report.

Table 1 - Licence Information

Environmental Protection Licence Number	11569
Licensee's Name	Hunter Quarries Pty Ltd
Licensee's Address	Licensee Postal Address: PO Box 3284 Thornton NSW 2322. Premises Address: Karuah Quarry, Corner of Andesite Road and The Branch Lane, Karuah NSW 2324.
Link to Full Licence on the EPA Website	EPL 11569

2. Dust Monitoring Results

There are no specific dust criteria listed in the EPL, but the following dust criteria (**Table 2**) are listed in Schedule 3 Condition 14 of DA 265-10-2004.

Table 2 - DA 265-10-2004 Dust Deposition Criteria for the Karuah Quarry

Averaging Period	Maximum Increase in Deposited Dust Level ¹	Maximum Total Deposited Dust Level ¹
Annual	2 g/m ² /month	4 g/m ² /month

Note ¹: Dust is assessed as insoluble solids as defined by AS 3580.10.1-2003.

SLR Consulting Australia Pty Ltd (SLR) undertakes depositional dust monitoring at Karuah Quarry. Monitoring is completed at the locations listed in **Table 3** below.

Table 3 – Air Quality Monitoring Locations for the Karuah Quarry

Site ID	Location	Address	GPS Coordinates
South (DDG 1)	South of the Karuah	5760 Pacific Hwy,	32°38'04"S
	Quarry	Karuah NSW 2324	151°59'58"E
South-East (DDG 2)	South of the Karuah	5770 Pacific Hwy,	32°38'02"S
	Quarry	Karuah NSW 2324	152°00'09"E
South-West (DDG 3)	South-West of the Karuah Quarry	DP 1024341, Karuah	32°37'57"S 151°59'41"E
East (DDG 4)	East of the Karuah	21 Halloran Rd	32° 37' 30.87"S
	Quarry	North Arm Cove NSW 2324	152°01'10.18"E

Appendix 1 Illustrates the air quality monitoring locations at Karuah Quarry.

Air quality monitoring was undertaken during the period 9 November 2017 to 7 December 2017 at the locations detailed in **Table 4**. Depositional dust gauge (g/m/²/month) results for this month and the year to date are shown in **Table 4**.

Table 4 – Insoluble Solids (g/m/²/month) for the Year to Date

	EPL Date Sampled		2047	
Date Sai	mpied 	7 December 2	2017	
Date	DDG 1	DDG 2	DDG 3	DDG 4
21/8/2013 to 18/9/2013	1.2	0.9	0.7	0.4
18/9/2013 to 17/10/2013	1.9	1.4	1.5	2.1
17/10/2013 to 18/11/2013	0.5	1.8	0.7	9.5
18/11/2013 to 16/12/2013	1.1	0.7	2.6	1.6
16/12/2013 to 13/1/2014	1.2	0.7	0.7	1.7
13/1/2014 to 14/2/2014	1.4	0.9	1.2	1.7
14/2/2014 to 18/3/2014	1.0	1.2	1.4	1.2
18/3/2014 to 16/4/2014	0.7	0.4	0.3	1.3
16/4/2014 to 15/5/2014	1.8	0.5	1.1	1.2
15/5/2014 to 1/7/2014	1.1	0.6	0.4	0.3
1/7/2014 to 31/7/2014	0.5	0.5	0.5	0.5
31/7/2014 to 29/8/2014	1.2	0.9	0.5	0.5
29/8/2014 to 25/9/2014	0.6	0.6	0.5	7.1
25/9/2014 to 24/10/2014	1.2	1.0	0.8	0.6
24/10/2014 to 22/11/2014	1.3	1.2	1.1	1.1
22/11/2014 to 22/12/2014	2.2	2.2	0.5	2.9
22/12/2014 to 20/1/2015	0.9	1.2	0.7	0.6
20/1/2015 to 17/2/2015	0.6	0.7	0.1	1.1
17/2/2015 to 18/3/2015	0.8	2.5	0.6	1.2
18/3/2015 to15/4/2015	1.0	3.0	0.8	1.1
15/4/2015 to 14/5/2015	1.7	3.7	1.1	1.2
14/5/2015 to 12/6/2015	0.3	1.0	0.4	0.8
12/6/2015 to 10/7/2015	0.5	0.3	0.2	0.3
10/7/2015 to 7/8/2015	1.6	0.9	0.7	0.7
7/8/2015 to 7/9/2015	1.4	0.4	0.6	2.1
7/9/2015 to 8/10/2015	0.8	0.4	0.3	0.3
8/10/2015 to 6/11/2015	1.3	1.2	0.6	0.5
6/11/2015 to 8/12/2015	2.1	0.8	2.8	4.1
8/12/2015 to 8/1/2016	6.4	0.9	0.6	1.2
8/1/2016 to 8/2/2016	1.4	0.9	1.1	1.2
8/2/2016 to 3/3/2016	4.0	0.7	0.6	0.9
3/3/2016 to 4/4/2016	3.1	0.3	1.0	2.0
4/4/2016 to 6/5/2016	1.5	1.1	0.4	3.2
6/5/2016 to 3/6/2016	1.0	0.9	0.7	0.4
3/6/2016 to 4/7/2016	0.4	1.6	0.5	0.3
4/7/2016 to 1/8/2016	1.4	0.7	0.3	0.5
1/8/2016 to 31/8/2016	2.7	3.0	0.8	0.7
31/8/2016 to 28/9/2016	2.1	1.6	0.8	0.8
28/9/2016 to 26/10/2016	0.8	0.6	0.8	0.5

	EPL	=	11569		
	Date Sampled		7 December 2	017	
	Date	DDG 1	DDG 2	DDG 3	DDG 4
20	6/10/2016 to 23/11/2016	0.7	1.0	1.3	2.3
23	3/11/2016 to 21/12/2016	1.3	0.5	0.9	1.0
2	1/12/2016 to 18/01/2017	0.4	0.8	0.7	2.5
18	8/01/2017 to 16/02/2017	1.3	0.9	1.2	1.2
16	6/02/2017 to 20/03/2017	0.4	1.4	0.5	3.8
20	0/03/2017 to 21/04/2017	0.6	0.7	0.5	0.8
2	1/04/2017 to 23/05/2017	0.6	0.6	1.1	0.8
23	3/05/2017 to 20/06/2017	0.5	1.3	0.9	1.2
20	0/06/2017 to 18/07/2017	0.4	0.2	0.5	1.2
18	8/07/2017 to 17/08/2017	0.6	0.5	0.6	0.5
1	7/08/2017 to 14/09/2017	1.4	0.2	1.4	1.5
14	4/09/2017 to 12/10/2017	1.1	0.1	1.2	1.8
1	2/10/2017 to 9/11/2017	1.7	0.5	0.9	1.0
	9/11/2017 to 7/12/2017	1.0	1.8	0.7	1.8
R	olling Annual Average	0.8	0.8	0.9	1.5

Monitoring results indicate that for the period 9 November 2017 to 7 December 2017 the insoluble solid levels recorded at DDG1 to 4 monitoring locations were below the project criterion of 4 g/m²/month.

3. Blast Monitoring Results

The following conditions in EPL 11569 refer to blast management.

- M6.1 The licensee must monitor all blasts carried out in or on the premises at or near the nearest residence or noise sensitive location (such as a school or hospital) that is likely to be most affected by the blast and that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee relating to alternative blasting limits.
- L4.1 Blasting in or on the premises must only be carried out between 0900 hours and 1500 hours, Monday to Friday. Blasting in or on the premises must not take place on weekends or Public Holidays without the prior approval of the EPA.
- L4.2 The overpressure level from blasting operations carried out in or on the premises must not:
- a) exceed 115 dB(L) for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and
- b) exceed 120 dB(L) at any time at any residence or noise sensitive location (such as a school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative overpressure level.
- L4.3 The ground vibration peak particle velocity from blasting operations carried out in or on the premises must not:
- a) exceed 5mm/second for more than 5% of the total number of blasts carried out on the premises within the 12 months annual reporting period; and
- exceed 10mm/second at any time at any residence or noise sensitive location (such as a school or hospital) that is not owned by the licensee or subject of a private agreement between the owner of the residence or noise sensitive location and the licensee as to an alternative ground vibration level.

Table 5 summarises the November 2017 blasting results.

Table 5: December 2017 Blast Monitoring Results

Date and time	Overpressure and Vibration	Monitor 1 (Weighbridge)	Monitor 2 (Nearest Resident)
04/12/2017	Overpressure dB(L)	112.8	110.9
12:25 pm	Vibration(mm/s)	1.97	1.68

As shown in **Table 5**, one blast was undertaken on 4 December 2017. This blast was below the overpressure and ground vibration criteria.

4. Noise Monitoring Results

Schedule 3 Condition 1 of the Development Consent requires Hunter Quarries to ensure noise generated by the development does not exceed criteria outlined in **Table 6** at any residence, or any noise sensitive receptor on privately owned land.

Table 6 - Development Consent Noise Impact Criteria - Karuah Quarry

Time Period	Noise Limit (dBA) LAeq(15minute)
Day	
7:00am to 6:00pm Monday to Friday	48
7:00am to 1:00pm Saturday	
Evening	47
6:00pm to 10:00pm Monday to Friday	47
At All Other Times	46

Table 7 illustrates the operator attended and unattended noise monitoring locations at Karuah Quarry.

Table 7 - Development Consent Noise Impact Criteria - Karuah Quarry

Noise Monitoring Location	Property Name	Distance from Karuah Quarry
NM1	Lot 3 DP785172	317 metres South of the Karuah
INIVII	5772 Pacific Hwy, Karuah	Quarry
NM2	Lot 2 DP 785172	200 metres South of the Karuah
INIVIZ	5760 Pacific Hwy, Karuah	Quarry
NM3	Lot 22 DP 1024341	370 metres South West of the
NIVIS	LOI 22 DF 1024341	Karuah Quarry

4.1 Operator Attended Monitoring Results

The results of the operator attended noise surveys are presented in **Table 8.** Ambient noise levels given in the tables include all noise sources such as traffic, insects, birds and quarry operations.

Table 8 - Operator Attended Noise Survey Results

Location	Date/Start Time/ Weather	Primary Noise Descriptor (dBA re 20 □Pa)					Description of Noise Emissions and Typical
		LAmax	LA1	LA10	LA90	LAeq	Maximum Noise Levels (dBA)
NM1	13/12/2017	80	74	70	63	68	Pacific Highway ~ 55-80
Lot 3 DP785172	16:03 Wind: 4.5 m/s NE Temp 31°C	Contribution not measurable above background noise.					Insects ~60-65 Quarry inaudible
NM2			75	74	69	72	Pacific Highway ~ 55-75
Lot 3 DP785172	Contribution not measurable above background noise.				Insects ~54-69 Quarry inaudible		
	Temp 31°C			ı			
NM3			70	69	59	65	Pacific Highway ~ 54-72
Lot 22 15:16 Wind: 4.5 m/s NE		Estimated Karuah Quarry Operations LAeq 47 dBA				Insects 39-48 Quarry inaudible	
	Temp 31°C						

4.2 Unattended Continuous Noise Monitoring

Unattended noise monitoring results for locations NM1 and NM3 are presented in Table 9.

Table 9 – Unattended Continuous Monitoring Ambient Noise Levels

INP Period	LA1	LA10	LA90	LAeq	
NM1	·				
Daytime during Operational Hours ¹	69	66	55	67	
Daytime outside Operational Hours ²	68	64	54	62	
Evening ³	66	63	51	59	
Night ⁴	67	64	52	61	
NM3	NM3				
Daytime during Operational Hours ¹	75	69	54	66	
Daytime outside Operational Hours ²	74	69	54	64	
Evening ³	75	69	49	65	
Night ⁴	75	69	39	63	

Note:

- 1. Daytime 7.00 am to 5.00 pm Monday to Friday, 8.00 am to 12.00 pm Saturday, not operational on Sunday
- 2. Daytime 5.00 pm to 6.00 pm Monday to Friday, 12.00 pm to 6.00 pm Saturday, 8.00 am to 6.00 pm Sunday
- 3. Evening 6.00 pm 10.00 pm
- 4. Night 10.00 pm to 7.00 am pm Monday to Saturday, 10.00 pm to 8.00 am Sunday.

4.3 Noise Results Summary

Operator attended and unattended noise monitoring was conducted at the three nearest residences to determine noise levels produced by Karuah Quarry operations.

The noise contribution of Karuah Quarry operations remained lower than that from the road traffic on the Pacific Highway during all attended noise surveys. The monitoring results indicate that compliance with the consent conditions were achieved at all noise monitoring locations during all periods.

Results from the ambient unattended measurements at locations NM1 and NM3 also indicated that Karuah Quarry is not a major contributor to ambient noise levels at each of these locations.

5. Surface Water Monitoring Results

Condition L2 of the EPL outlines the requirement to monitor surface water discharges from the Karuah Quarry via the licensed discharge point (LDP001).

Table 10 summarises discharge monitoring at Karuah Quarry.

Table 10 - Surface Water Discharge Monitoring Results

Sampling Point	Monitoring Frequency	Pollutant	Pollutant Measurement	
LDP001	During Discharge	pH TSS	No discharge during December 2017	6.5 – 8.5 50

APPENDIX 1 Monitoring Locations





10 KINGS ROAD NEW LAMBTON NEW SOUTH WALES 2305 AUSTRALIA T: 61 2 4037 3200 F: 61 2 4037 3201 www.slrconsulting.com

The content contained within this document may be based

on third party data. SLR Consulting Australia Pty Ltd does not guarantee the accuracy of such information.

riojectivo	033.1101 00.0030
Date:	23/06/2014
Drawn by: LH	
Scale:	1:12,000
Sheet Size:	A4
Projection:	GDA 1994 MGA Zone 56

Hunter Quarries Pty Ltd

Environmental Services and Support

Karuah Hard Rock Quarry **Environmental Monitoring Locations**

FIGURE 1